



Estimate

DATE	ESTIMATE #
2/18/2021	7578

Markesan, WI 53946

Fax #
920-398-8026

NAME / ADDRESS
Cottage Grove Fire Department 4030 County Road N Cottage Grove, WI 53527

Ship To
Cottage Grove Fire Department 4030 County Road N Cottage Grove, WI 53527

P.O. NO.

ITEM	DESCRIPTION	QTY	COST	TOTAL
	S1			
	Unit keeps purging air, found air system filled with a grease type material, most likely from a bad air dryer filter. Test system and replace air governor, and air dryer, system needs a compressor and will have to be installed at the shop due to the location.			
	Work done so far			
Misc. Parts	B2B D2 air governor	1	30.44	30.44
Misc. Parts	wabco air dryer	1	272.00	272.00
Mileage	Mileage to and from Fire Station	120	1.10	132.00
Labor	diagnose and install governor and air dryer.	2.75	115.00	316.25
Labor	To remove air compressor	4.5	115.00	517.50
Shop Supplies	Misc. Shop Supplies	1	10.00	10.00
	Work to be done			
Misc. Parts	high cfm low profile air compressor cummins	1	2,224.19	2,224.19
Core Charge	Core Charge	1	166.99	166.99
Freight	Freight charges TO BE DETERMINDED	1	0.00	0.00
Labor	To install compressor and test system.	4.5	115.00	517.50
Shop Supplies	Misc. Shop Supplies	1	20.00	20.00

Any questions please call Manny at 920-398-1033

TOTAL \$4,206.87

Thank you!!

SIGNATURE/DATE _____